

Arbitrary scale, higher is better	General Corrosion	Pitting Corrosion	Crevice Corrosion	Erosion Corrosion	Cavitation	Stress Corrosion
Bronze	8	9	9	7	5	
NiAlBrnze	9	10	8	8	8	10
Ni-Cu Alloy	10	5	2	10	8	?
Carbon	3	3			2	
Stainless	10	4	3	10	7	8
6Mo	10	9	8	10	8	8
Duplex	10	5	4	10	8	9
Superduplex	10	9	8	10	8	9
Ni Alloy 625	10	13	12		13	
Ni Alloy C22	10	14			10	
Titanium	10	15	10		9	

